

STA. 195
DATA CONTROL STA.
MAINTENANCE
LOG
COMM. DIV.

12-19-72

GD 346



DIAL

THE DEER



GRAVER-DEARBORN CORP.

1445 W. JACKSON BLVD.

CHICAGO, ILLINOIS 60607 PHONE 226-6100

12-19-72 Tested spare computer cards
from STA. 108. T.C.L.

12-20-72 Tested spare computer cards
from sta. 108. The computer would
bomb then the room temperature
would go above approx. 72° - 74° .
so I run test to look for the
problem. Found 2 connector pins
on card H-10 on the mainframes were
widely spaced apart. T.C.L.

12-21-72 - Run some more test on the high
room temperature bomb out of the
computer. Also checked all the computer
cards for connector pins that were
widely spaced apart and repaired.
The computer would run good up
to approx. 87 - 88° . T.C.L.

12-26-72 - Made a absolute mainframe exercises
tape # 303001B and a absolute Inst.
Simu. + Comp. tape # 303002B. Also
run the Interface diagnostic
communication test back to back.
T.C.L.

1-25-73 Cleaned all air filters. Run the Communication test program and checked RFL levels and freqs. T.C.L.

2-27-73 Chicago wasn't always receiving a signal from STA.195. Run the comm. Test program and checked RFL levels and freqs. The carrier freq. was 1696 and the BF osc. was 28.2998 Mc. Reset to 170 cps. + 28.3 Mc. Run the test program back to back for 1 Hr. and there were no ~~no~~ errors typeout. T.C.L.

3-14-73 Installed a modified Carrier detector alarm ^{HB-21025} ~~with~~ with a carrier cut off circuit then the carrier is locked on that came from the shop at STA.106. Checked it out and it worked ok. T.C.L.

3-23-73 Cleaned all air filters.

Using the new Modified to upper 16K loader program I run the following diagnostics 303001B, 303002B, 303003B, 303004A, 303005B, 303006B, 303007C, 303008C, 303010A, 303014A, Interface Diagnostic prog. and the interface

Diagnostic and every thing checked ok.
Checked of the RFL carrier cut off circuit
in the Carrier detector alarm HB-21025
and found that the relay MRB 2006
was sticking needs to be replace and
#106 shop is sending one out, T.C.L.

3-30-73 Replaced the bad Carrier detector
alarm mod. HB-21025 with one
from STA.106 shop. And run the
Comm test program to check out
the carrier cut off circuit and every
thing checked out ok. T.C.L.

4-26-73 Run the Comm. Test program
and checked RFL levels & freqs.
Also run back to back because
gas control said STA.195 & 199 was
intermitt. Everything checked ok. T.C.L.

4-30-73 Run the Comm. Test program
and checked RFL levels & freqs. Also
run the back to back test. Everything
checked ok. T.C.L.

4-27+29-73 Col. football equipment

5-23-73

5-4-73 Run the Comm. test program and
ched the RFL levels + frogs. also run
back to back test. Ched Mod. + Demod
levels on the MC-50 ch. 30 + 32. Everything
ched. ok. T.C.L.

5-7-73 Teletype lubrication. T.C.L.

5-11-73 Run the Comm. test program and
ched the RFL levels + frogs. also
run back to back test. Ched Mod
+ Demod. levels on the MC-50 ch. 30
+ 32. Everything ched. ok. T.C.L.

5-21-73 Run the comm. test program and
ched the RFL levels + frogs. also
run back to back test. Ched Mod.
+ Demod levels on the MC-50 ch. 30
+ 32. Everything ched ok. Cleaned
the connectors on the RFL. drawers, T.C.L.

5-23-73 Run the Memory Worst Case
diagnostic program No. 303010A
for 20 min. Everything ched ok,
also re-run the Comm. Test program
back to back and everything ched.
ok. T.C.L.

5-30-73 checked all power supply voltages and reset the 3.6 V, 5V, and 21V power supply. checked the AC voltage into the computer and it was 113.5 Volts. checked the voltages from the Line Drivers, current drivers and inhibit driver regulators 8269 and reset R7 output voltage. checked the Memory timing on 8270. checked the voltage on the Threshold regulator 8277 and reset the 12V with R11, it was 12.3 Volts. R6 was ok. Checked the Power fail safe 8296 and everything was ok. T.C.L.

6-1-73 Checked all power supply voltages. checked the voltage on the threshold regulator 8277 and reset the 12V with R11. checked + reset the voltages from the Line Drivers, ~~the~~ Adj. the read + write current from the current drivers. Rins the the Mainframe speciser 303001B, Compare Memory to "A" and Memory worst case 303010A and everything checked ok. T.C.L.

6-7-73 + 6-8-73

Readjusted all power supply voltages.

Readj. voltages on the line driver cards
8269 on both memories. Also readj. voltages
on the threshold regulator cards. 8277.
Adjusted the read and write currents on the
dual current drivers card No. 8959.

But then I was running the memory
worst case diagnostic tape 303010A using
the upper 16K loader it would lose a 1
in bit 12 of locates 10732 + 10721.

Went using the 8K loader, everything was
ok then running the worst case diagnostics
checked and repaired bad pins on the back of
the cards used for the old + New memory
but it still didn't work. Found out by
reversing the line driver cards 8269 from
both memories and running the worst case
diagnostic tape it would work ok. ^{Re}checked
the line driver voltages, read + write
currents but nothing had changed. Reversed
the cards back to the original way and
the worst case diagnostic would not
run. So I reversed the line driver

and frogs, and also seen back to back. Everything checked ok. T. C. L.

6-26+27-1973

Run the room temp up to see how the computer would run. And found out that it would bomb out at approx. 80° to 82° . Checked all cord pin widely spaced pins and repaired widely spaced pins. Then the computer would go up to approx. 90° before it would bomb out. T. C. L.

7- 9+10+11

The control panel reading such as mainline suction pressure, mainline discharge pressure and etc. would go to their min. value intermittently when running the programs tape. Run the following tapes ok, 303002B, 303005B, 303006B, 303001B, 303014A, and 303010A. Then running the interface diagnostic tape in the A/P conversation test the read outs would intermittently go to min. Found a pin AV in connector P6 on the back of rack 1F2 that was not

push all the way in, so I repaired. Then
the A/D test worked ok all the time.

Also run the program tape to see if
want temp the program would bomb out
and it was at approx. 48° . Run the
composite diagnostic program tape, ~~to~~
~~it~~ add everything checked. T.C.L.

7-19-73 + 7-20-73

Had a problem in the A/D section
of the computer and the computer wouldn't
read out the presses and etc. Found a
bad transistor Q₃ 2N3503 on card
43321 \approx driver. and also card No.
43326 had a intermittent trouble which
Alan took back to Beatrice to repair.
Also installed a transient suppressors
on the Porax and the computer ^{A.C.} inputs.
The ~~led~~ out 10 times ^{on-off} and the
computer didn't bomb out. But the porax
didn't come on 3 times. T.C.L.

7/25/73 The ~~to~~ program would intermittently
bomb out. Ran the memory worst
case tape for approx. 1 Hr. and got
2 mistakes. It would lose a bit
in bit 14 at different locations. Chkd
and repair all pins on the cards for
both memories. But this didn't seem to
help. Chkd voltages on current driver
card 8269 and readj. the voltage on
6K18 for 18.4 volt which was low.
Chkd the voltages on the threshold
regulator card 8277 and everything
was ok. Chkd the current driver
8959 read + write current and everything
looked ok. Rerun the memory worst
case tape for 1 Hr. and everything this
time worked ok. T. C. L.

7/31/73

On 7-30-73 the parox was removed
and the Solatrom was hooked back up. So
I reched. the solatrom voltage and reset
all the power supply voltage in the computer.
Readj. voltage on the line driver cards 8269
on both memories also readj. voltage on

the threshold regulator cards 8277,
adjusted the read + write currents
on the dual current drivers cards, No. 8959,
Ran the memory worst case diagnostic
tape 303010A and everything checked ok.
Turn the power to the Dulator on & off
10 times and everything checked ok. T.C.L.

8/2/73

Run the Data Modem + Communications
test program ^{DCS#2} back to back ~~and~~ checked
and reset RFL levels & freqs. It played
one hour back to back with out a error.

8/3/73 + 8/7/73 + 8/8/73 + 8/9/73

The computer would intermittently bomb
out when turning on-off the power to
the Dulator, and sometimes the loader
tape and the program tape would not
load back in the computer. Checked all power
supply voltages and line driver voltages and
read & write current and ready, ~~if~~
if need but none were all about weight.
This didn't seem to help the problem.
On 8/7/73 change out the memory cards

one at a time with spares from Beatrice but was unable to locate the problem.

On 8/8/73 I found by replacing card No. 4639 Data cover the computer would work ok.

8-13-73 + 8-14-73

Worked on the computer looking for the intermittent problem of the computer bombing out when the power was turned on + off. Had no luck. T.C.L.

8-14-73

Replaced the spare A-D card No. 83326 with the one that Alan took to Beatrice 7-20-73 that had a intermittent problem in it and he repaired.

Also the TTY reader didn't work and found a short diode CR3 in the reader power supply. Replaced the bad diode and the TTY reader worked ok. Tried turning the computer power on + off approx. 30 times and everything checked ok. T.C.L.

6-17-73

Replaced bad nickel-cadmium
batteries 12 volt in the paracom clock.
T.C.S.

8-23-73

Readj. the RFL levels + freqs.
Installed the Low freq. clock cord No.
8717 in the TTY that was repaired
at do. 104. T.C.S.

8-30-73 Cleaned all air filters in the computer.

Added some grounding straps to
the computer. Checked the RFL levels &
levels and everything was ok. T.C.S.

9-5-73 Wnen through the adjg procedures
for the RFL Modem and checked Freqs.
& level of the RFL. And everything
checked ok. T.C.S.

Also the Paracom digital clock would
go to zero month, zero days, and zero
hours then the A.C power then off and then
back on. Cleaned the relay K1 in the

PM12E3-P200 power supply and then
the clock would hold like eight months,
days, and hours. T.C.L.

Sept. 7, 10+11

Calibrated Forebore equipment. T.C.L.

Sept. 21, 1973

Ran the Comm. test Program because
Gas Control was getting a poor report.
The RFL Levels & Pres. all look good,
Also the MC-50 Mid & Period level look
good. Also it played back to back for 1 Hr
and no error. T.C.L.

Sept. 27, 1973

The Paraban clock would intermittently
lose the Month & Day (go back to 1 Month
& 1 day) when the A.C power would go on & off.
Found a leaky transistor Q1 40251
in the Power supply board assy, 341857
and replaced. Also found a leaky transistor
Q7 2N1539 on the Power supply PM12E3-P200
but didn't have one so I ordered one from

the shop at \$6.10 and when I receive
it I will replace the bad transistor.

T.C.L.

Oct. 3, 1973

Replaced a leaky transistor Q7 2N1539
in the power supply PM12E3-P200 and
then turned the power on-off several times
to ch. that the Month + Ray didn't go
back to one month + one day and everything
checked out ok. Also run the Comm. test
program and did the RFL levels +
Freqs. Also run boot to boot for
45 mins. and everything checked out ok.

T.C.L.

Oct. 4 & 5, 1973

At 10:00AM 10/4/73 the computer booted
out when the A-C power was turned out off.
then was unable to load in the bootstrap
loader. Checked the operation of the enter
switch on the control panel by grounding
pin 13 of IC-14 and putting the enter
switch up and with the scope on pin 10

of IC10 look for a. He went pushing
down on the stop switch. Everything
checked ok. Checked the read to write currents
from the lower 8K current driver card
#8959 and found that the X-read
current was only 200 ma. went it should
be 360 ma. Was unable to adj. the
current. Found the transistor Q3,
2N3134 was open and it replaced.
Readj. the line driver #8269
voltages and readj. the X-read
current to 360 ma. The computer
checked out ok. after completing the
above.

Oct. 19, 1973

Completed the following chs. on
the computer. A₁-A₆, B₁+B₃, C₁ + C₂
C₂ power supply voltages.

Model 222 (-6V = -5,865 volts) (-10V = -9,587 volts)
(-16V = -15,061 volts) (+40V = +33,450 volts)
(+16V = +17,381 volts) (+35V = +33,176 volts)
(+21V = +21,066 volts)

Model 223 (compacto main frame)

3.6 volts = 3.596 volts

Model 221 3.6 volts = 3.606 volts

5 Volts = 4.961 volts

Model 223 (Far right interface rack)

3.6 volts = 3.600 volts

C3, C4 (A-accumulators = 105)

C5, D4, D6, T.C.L.

Oct, 24, 1973

Completed the following checks on the computers, P₁, P₂, P₃, P₅, D₇. T.C.L. (Computer A-C input voltage 117.5 K.A.C.

Nov. 2, 1973

Received a new program tape dated 10/25/73 but one was damaged in shipping so I made a new tape with the spare, loaded in the new tape into the computer and checked it out in locate control and everything seems to check out ok. Reloaded in the old tape dated 7/3/73. T.C.L.

Nov. 5, 1973

Loaded in new program tape dated 10/25/73 and checked with Chicago and everything checked ok. T.C.L.

Nov. 7, 1973

Run the Comm. Test program & checked the RFL levels & frays, run back to back for 1 Hr. and there were no errors. T.C.L.

Nov. 26, 1973

Run the Comm. Test program & checked the RFL level & frays. Run back to back for 1 Hr. and there were no errors. The computer bombed the night of 11/23/73 so I ran the following tape, Memory worst case, Compare memory to 'A', Memory test, & the PWR Fail-outlet result and everything worked ok. T.C.L.

Also cleaned all air filters in the computer.

Dec. 5, 1973

On 12-4-1973 the operator was unable to reprogram the computer. I found that when loading in the loader tape it wouldn't stop at the end but would go all the way through the reader. Also the teletype motor wasn't running. Replaced a 2 1/4A SLO-BLO fuse pod No. 165734 and then everything worked ok. Ran the Memory worst case tape 303010A and the composite diagnostic program tape and everything checked out ok.
T.C.L.

Dec. 18, 1973

Ran the Comm. test programs and checked the RTL levels + freqs. Ran back to back for 1 1/2 hrs. with no errors. Everything looks ok. T.C.L.
The carrier from Chicago was 1696 cps.

Dec. 19, 1973

Cleaned all the computer + interface air filters. Installed gm. wire to the 2R1, 2R3 sleds and also between the

middle interface rack and the mainframe
rack. 1 Hr. T.C.L.

Dec. 19, 1973

The computer bombed about 3 p.m.,
and I was unable to load in the loaded
tape. By leaving the covers to the memories
off and the main frame door open the
computer would run ok. The problem was
intermitt. (work overtime 2 hrs.) T.C.L.

Dec. 20, 1973

Worked on the problem above but the
computer worked ok all day until about
2:15 PM, and then it was very intermittent
and was unable to find any thing wrong. T.C.L.
(work 4 hrs.)

Dec. 21, 1973

Worked on the problem above.
When the upper 16K memory cover plate
was off and the mainframe door open the
memory voice case tape worked ok. But
when the cover was on and the door closed.

after approx. 15 to 20 min the memory would
bomb out. Was unable to find the problem
so I left the cover off and the door open.
(10 1/2 Hrs.) T.C.L.

12-26-73

Worked on the above problem.
Ran the room temperature to 88° F
before the memory worse case tape
would bomb out. Never did get the
computer to bomb out at normal temperature.
6 Hrs. T.C.L.

12-27-73

Ready, the computer modem from
2000 Bits-per-second to 1667 Bits-
per-second. Played back to back for
1 1/2 Hrs with out a error. (4 Hrs.) T.C.L.

12-28-73

The computer bombed out 2 times
because of A-C failed but was unable
to find any thing wrong + was unable to
get the computer to bomb out. T.C.L. (4 Hrs.)

1-2-74

Worked as a intermittent bomb out problem but was unable to get the computer to bomb out. Run the composite diagnostic program tape without any errors. (5 Hrs) T.C.L.

Also run the room temperature up to 86° without a bomb out.

1-4-74

Run the comm. test program + check the RFL levels + frqs. Run back to back for $1\frac{1}{2}$ Hrs. without a error.

Chicago did say that on 1-2-74 + 1-3-74 the computer didn't report every good.

T.C.L. (4 Hrs.)

1-9-74

Run the comm. test program + check the RFL levels + frqs. Run back to back for $1\frac{1}{2}$ Hrs. without a error. Check all air filters. T.C.P. (5 Hrs.)

1-15-74

Replaced 2 bad fura meters
one in the middle interface rack
model No. 80-004 and the other one
in the 3.6V power supply in the West
rack the fura model No. 4500 D.C.L. 3Hrs.

1-21-74

The programmed bombed on the
1-18-74, 1-19-74 so I run the
following diagnostic tapes to
see if I could find any thing wrong:
Memory worst case 303010A, Load/store 1
Reg. test. 303005B, Instn. Senses. +
Comp. 303002B Mainframe Exercise
303001B and the Interface-Map.
Verify test 303014A and everything
died out ok. D.C.L. (4Hrs.)

1-25-74

Replaced a bad fura meter on the
model No. 222 power supply. Adj. the
21 net pot. Residjed. the power fail
safe card. 4296 at location 96. 4Hrs,
D.C.L.

1-31-74

Did the following routine maint.
A3, A4, A5, A6, B1, B3, T.C.L. (4 Hrs.)

2-27-74

Did the following routine maint.

A1, A2, A3, A4, A5, A6.

also was teletype was making a little noise so I oil some point around the motor and it sounded much better. (5 Hrs.)
T.C.L.

3-6-74

Gas Control reported that the computer didn't report back 18 times last night.

Chk. the RFL frogs and levels and everything else ok. The Computer played back to back for 45 min. without a mistake. Reset

Ch. 30 mod. amp. leads and Ch. 26 demodamp. lead.
T.C.L.

3-20-74

Revised the RFL Modern adj. procedure as to the March 15, 1974 letter changing the

bit per second from 1667 BPS to 1200 BPS.
Chk the RFL levels + freqs. and play back
to back for 45 min. without a error.
Chk with Ron Tapsen at Chicago and
everything chkd. out ok. T.C.L. (4 Hrs.)

3-22-74

Did the following maint. on the
computer. A₂, A₃, A₄, A₅, A₆, B₁. T.C.L. (2 Hrs.)

3-29-74

Chk the computer RFL freqs. + levels
and run back to back 1 Hr. without
a error. Chk with Ron Tapsen at Chicago
to see how it was reporting & everything
seem to be ok. T.C.L. (1 1/2 Hrs.)

4-11-74

Did the following Semi-Annually
routine maint. on the computer. A₂, A₃, A₄, A₅, A₆,
B₁, B₃, C₂, C₃, C₄ - "A-ocum" 105, C₅,
Power Supply voltages



4-11-74

Model 222

$$-6V = -5.870 V.$$

$$-10V = -9.580 V.$$

$$-16V = -15.295 V.$$

$$+40V = 33.170 V.$$

$$+16V = 17.375 V.$$

$$+35V = 33.154 V.$$

$$+21V = 21.000 V.$$

Model 223

$$3.6 \text{ Volts} = 3.620 \text{ Volts.}$$

Model 221

$$3.6V = 3.6 \text{ Volts.}$$

$$5V = 5.003 \text{ Volts.}$$

Model 223 (For right interface reader.)

$$3.6 \text{ Volts} = 3.620 \text{ Volts.}$$

6 Hz. T.C.S.

4-15+16+17 - 74

Cal. Forboore equipment. T.C.S.

4-19-74

When through the photodiode amplifier adjustments on the high speed reader using the neutral density filter. T.C.S. 2 Hz.

5-7-74

Ran the following monthly maint.
on the computer. A₂, A₃, A₄, A₅, A₆ P.C.L. (H₂)

5-17-74

The computer bombed out 3 times
between 5-16-74 + 5-17-74 so I running

the following diagnostic tapes

303001B, 303002B, 303003B, 303004B,

303005B, 303006B, 3030070,

303008C and 303010A without a

error. Also checked the Proc. fail auto
restart circuit and it worked ok.

6th. P.C.L.

5-19-74

The computer bombed two times ~~on~~
5-18-74 and two times on 5-19-74. When I
got here Sunday night the computer
displays reading were all reading wrong.

But when I reprogrammed everything
was ok. Ran the following diagnostic
tapes 303010A Interface diagnostics
PCS #1 and everything was ok. P.C.L.

5-20-74

The computer bomb out at about 9:30 A.M.
Reset 3.6 + 5.0 Volt power supplies.
Read the memory voltages + read
& write currents in both memories.
Readj. the power fail circuits. Run the
memory worst case tape and run the
temperature up to 84° without a error.
Turn the power on + off approx. 10 times
and the computer bomb out 1 time.
6hrs. T. C. L.

5-21-74

Turn the power on + off to the computer
several times without a bomb out. Recheck
the 3.6 V + 5.0 volt power supplies.
Found that the 5.0 Volt power supply
was varying. Found a loose pin in connector
CD-7 on the violet wire which is the 5.0 Volt
wire. Run the composite diagnostic program
tape without a error. T. C. L. (6hrs.)

6-6-74

Rid the following monthly maint.
on the computer: A2, A3, A4, A5 + A6.
(1 Hr) T.C.L.

6-21-74

The computer missed ^{reporting} 11 times the
night before. Chkd the RFL levels +
freqs. and also chkd the Mod. + Parah
level on the MC-50 multiplex but everything
chkd ok. Ran the common test back to
back for 1 Hr without a error. T.C.L. 1 1/2 Hr

6-26-74

Chkd the RFL levels + freqs because
Chicago said the computer wasn't reporting
back all the time. Everything look
ok. Had Ron Tjepson at Chicago take
a look at Linc Control to see how
stn. 195 was reporting back. It wasn't
reporting back as good as the other
stations so I made a small adj in the
bias + balance adjustments. T.C.L. 3 Hr

6-28-74

Checked the RFL levels & freqs. because Chicago said the computer wasn't reporting back all the time, Ready. the bias & balance on the FS Receiver H B-21045 and run back to back without a error for 45 mins.

T.C.L.
(2Hrs)

7-1-74

Checked the RFL levels & freqs because Chicago said the computer was reporting back slow on the readouts, Everything checked out ok. Also checked the operation of the Schmitt trigger and it was working ok.

T.C.L.
(2Hrs)

7-3-74

Checked the RFL levels & freqs because Chicago said the computer was reporting back slow on the readouts. Everything checked out ok. Ready R7 on the Freq. Clock Card in slot 12A on Rm Jeps in Chicago said the readouts were coming in real good.

T.C.L. (2Hrs)

7-5-74

The computer report looks to Chicago the night before approx 37%. Racked the RFL levels + freq. and everything checked out ok. Readj. the low freq clock card. R7 at loc. 12-A. Chel with Ron Tepsen in Chicago to see the read outs where working. T.C.L. (2/1/2)

7-9-74

Run the composite diagnostic program tape without an error. But was unable to complete running the tape because of the lack of time. (Nash) The tape had several holes (5 Hrs. T.C.L.) with dirt in the holes and the tape would stop on me and I would have to start over.

7-10-74

Run the composite diagnostic program tape without an error. Replace the RFL modules with spore from Beatrice and run the comm. test program. (6 hrs T.C.L.)

7-23-74

Replaced all the RFL modules with
sto. 195 modules, replacing the spare RFL
modules from sto. 106. Run the com. test
program and set all freqs. + level.
Run back to back for 30 mins. without
a error. Reprogrammed with the sto.
program lounge and there were very
few interrupts. Ched with Ron Tepsen
in Chicago and he said the computers
were reporting very good. T.C.P. (3Hrs.)
Also replaced the I/O sync card No 9712
& the Galax C.O. card No. 9705 in location
2R1.

7-26-74

Run the Inst. Simul. + Compz test
program with 98 successful cycles
without a error. T.C.P. (1Hr.)

7-30-74

Changed around the two Priority Interrupt
cards. No 8242 at location 1R1 2A + 2B.

7-30-74

Run the com. test program and checked the RFL equipment. Played back to back for 45 min. without a error. Chd with Chicago to see how the computer was reporting but the master computer wasn't working. T.C.P. (2 Hrs.)

7-31-74

Run the Proc. Fail-out restart scope and chd out the proc. fail circuit and everything chd out ok. Run the Inst. Simu. + Comp. test program and I had a few errors. Found two pins on card. 8206 at location E-5, that were space apart and repaired. Replaced the following cards at location 2R1, 25A, 13A, 10A, and run the com. test program to ~~the~~ the RFL. Chd the comm. between SAs-195 + Chicago. (7 Hrs.) T.C.P.

8-9-74

Run the composite diagnostic program tape without an error. Replaced the micro switch on the high speed reader. T.C.L. (4 hrs).

8-14-74

Did the following annual maint. on the computer C2, + C4

Model 222	Ripple	Model 221	Ripple
-6 = -5,4692	- 19 mv.	3.6V = 3.60	- 6.3 mv
-10 = -9,594	- 7.4 mv.	5.0V = 5.00	- 11.2 mv.
-16 = -15,190	- 36 mv.		
+40 = +32,981	- 2.8 mv.	Model 223	
+162 = 17,40	- 1.6 mv.	3.6 - 3,602	- 1.45 mv.
+35 = 33,178	- 3.2 mv.		
+21 = 21.00	- .59 mv.	Model 223 (For night)	
		3,6V = 3,6V.	- .64 mv.
		T.C.L. T.C.L. (6H2.)	

8-19-74

Checked all current drive voltages and all read & write currents. Checked the memory timing on cards 8270 and ready the No. 2

memory from 460 nanoseconds to 520 nanoseconds. Run the memory worst case program 303010 A for $1\frac{1}{2}$ Hrs. without an error. T.C.L. (4Hrs.)

4-21-74

Chd + readjusted the photodiode amplifiers in the High speed read using the neutral density filter method. Replaced a bad dr 8 photodiode CR9. T.C.L. (3Hrs.)

4-22-74

Did the following annual routine maint. on the computer.

A₁ - A₆, B₁, D₂

Rechecked the line driver voltages + the read + write currents of both memories. Also rechecked the memory timing on the 6270 cards.

Run the memory worst case tape without an error. T.C.L. (5Hrs.)

2-23-74

The computer was going into a I/O hold with a A-C power failure and sometimes it would bomb out.

Rechecked the line driver voltages & read & write currents. Try the spare line driver cards & the spare current drive card but it didn't seem to work any better. Reset the read & write currents to approx. 380 MA. and everything checked ok. Run the memory noise case tape for 1 Hr. without an error. Turned the power on & off several times without an error. D.C.L. (6/12)

8-26-74

Did the following annual routine maint. on the computer.

B₂, C₅, P₁, D₄, D₅, D₆. D.C.L. (4/12)

8-27-74

Did the following annual routine maint. on the computer. C₃,

also check the read & write currents in both memories. (D.C.L.) (6/12)

8-28-74

Run the 3½ hrs. composite diagnostic program tape without an error. (T.C.L. 3½ hrs.)
Cal. Foxboro equipment. (6 Hrs.)

8-29-74

Cal. Foxboro equipment (3 Hrs.) T.C.L.

8-30-74

Cal. Foxboro equipment (5 Hrs.) T.C.L.

9-4-74

Cal. Foxboro equipment. (3 Hrs.) T.C.L.

9-5-74

Cal. Foxboro equipment. (4 Hrs.) T.C.L.

9-17-74

Tried to improve the shape of the write + read pulses of memory #1 by exchanging the memory cards of memory #1 with the spare cards from sta. 104
No. improvement 5 Hrs. (T.C.L.)

9-18-74

Same as 9-17-74 also the computer was intermittently going into a I/O hold & sometimes into a halt until the power was turned on + off (6 1/2) Hrs

9-19-74,

Exchanged cards No. 8242 at location 6A+2B and the problem with the computer, intermittently going into a I/O hold + sometimes into a halt until the power was turned on + off went away. After exchange the cards back the way they were and still the problem was gone. Also checked D₂ that all outputs from the inputs to the DCs are operational. (6 Hrs.)

9-²⁶⁻⁷⁴ Worked on the above problem but was unable to find anything wrong. (4 Hrs.) TCR

9-27-74

There was noise on the computer Jc 30 and I found that card No. 8712 at location 2R1 20A was causing the problem.

Also the char. Mod. card MU40B-2 in the
ch. 30 mod. amp. was making a bad
connection in the connector. Also checked
the RFL bulbs and levels and adj.
the OE osc. 2 Hz. + the carrier 2 Hz.
(4 Hrs) T.C.P.

9-30-74, 10-(1+2+3+4)-74

The computer would intermittently go
into a I/O hold when the power was
turned on + off. Also the memory worse
case tape would not run without a error.
Replaced a bad data cover card No. 8639
and a bad wa sense amp. card. 8962
both on the upper 8K off memory.
Also replaced a bad transistor Q₁ 2N3772
in the upper 8K off memory. 28 Hrs T.C.P.

10-8-74

Ran the memory worse case tape
for 2 Hrs. without an error. Turned the
power on + off 40 times without an
error or I/O hold. 4 Hrs. T.C.P.

10-9-74

Run the composite diagnostics program tape without an error. (4Hrs.) T.C.L.

10-17-74

Did the following monthly maint.

A2 - A6. T.C.L. 1 1/2 Hrs.

Also run the memory worst case tape for 2 Hrs. without an error. Check the watch dog relay. 3 Hrs. T.C.L.

11-4-74

Put the following repaired cards from the shop at slot 106 back in the computer. 4712 at loc. 2R1-2A, 4639 at loc. H-20 of memory #2, and 4962 at loc. K-6 of memory #2.

Turned the power on & off 15 times without an error. Run the memory worst case tape No. 303010A for 1 Hrs. without an error. T.C.L. (4Hrs.)

11-12-74,

The computer went into a I/O hold
on 11-11-74 + 11-12-74 with a A-C power failure.
Reset the line driver voltages for
both memories. Turned the A-C power
on + off 10 times without an I/O hold.
T.C.L. (2/12)

11-18-74

Did the following month maintenance
on the computer. A₁ - A₆.

Run the memory worst case Test 303010A
but I would get errors every 15 or 20 min
when the computer cabinet doors were close.

When the doors were open I wouldn't
get any errors. Unable to find the
problem so I left the doors open. T.C.L. (4/12)

11-20-74

Run the input logic closed loop
diagnostic program + chkd all
input + output relays. Everything
chkd ok. Chkd out the unit I start
circuit and everything was ok. A.C.L.

4/12

12-11-71

Did the following routine maint. on the computer. A₂-A₆, B₁-B₂,
Oil the teletype motor and adj. the tension so that the motor wasn't so noisy. Ched out the ch. 45 Bit 15 + ch. 46 Bit 15 out from the computer + to the Terminal Box,
3 Hrs. to CL.

12-27-71

The computer read outs were not operating right. Found a bad RTL-MTY / DIV control 4 card No. 8286 at loc. 13B in the mainframe and replaced it with a spare card from slot 106. 3 Hrs. to CL.

12-30-71

Run the composite diagnostic program tape without an error. 3 1/2 Hrs. to CL

1-13-75

Replaced a repaired computer card
flout was repaired at the shop at
sta. 106. Card No 6203 at loc. 226.

Ran the composite diagnostic
program tape without an error.

3 1/2 hrs. T.C.L.

1-15-75

The Solatron power for the computer
was moved + checked + reset
the output voltage going to the computer.

1/2 hr. T.C.L.

1-16-75

Did the following monthly
computer maint. A2-A6. Replaced
the following parts in the teletype,
the motor intermediate gear motor pinion,
because the gears were making excessive
noise.

T.C.L. 4 hrs.

1-27-75

Replaced a required card No. 8286 at loc. 13B in the computer. The card was repair at sta. 106 shop. Run the following test tapes without an error. Multiply test, Divide test, Memory Word case tape and the composite diagnostic program tape. (T.C.D. 4 hrs.)

2-10-75

Did the following routine maint. on the computer A₁-A₆, B₁ + B₂.

2-19-75

Did the following routine maint on the computer C₂, C₄, C₅.

Power supply voltages

Model 222	Ripple	Model 221	Ripple
-6 = -5.860	2 mV.	3.6 = 3.582	2.2 mV.
-10 = -9.630	2.5 mV.	5.0 = 5.008	3.4 mV.
-16 = -14.840	340 mV.	Model 223	
+40 = 32.927	2.9 V.	3.6 = 3.596	.9 mV.
+16 = 17.357	1.7 mV.	Model 223 (Far right)	
+35 = 33.120	3.3 mV.	3.6 V = 3.6	.68 mV.
+24 = 21.000	5.5 mV.		

2-19-75 Also replace C3 .003 up/d cap,
on the auto start relay 82240. 4Hrs.

2-27-75

Clean, lubricated, and check the operation
of the teletypewriter. 4Hrs. T.C.L.

2-28-75

The computer bombed at 8:30AM.
Run the memory worse case loop for 20 min
without a error. T.C.L. 1/2Hr.

3-10-75

Cal. the Foxboro pressure controller
and Unit 1 + 2 surge valve controller.
T.C.L. 4Hrs.

3-11-75

Cal. the Foxboro equipment. T.C.L. 4Hrs.

3-19-75

Did the following monthly routine
maint. of the computer A2-A6 T.C.L. 2Hrs.

4-4-75

Modified the room temperature thermostat and cal. Added some grounding straps to the computer interface. 4 hrs. T.C.L.

4-7-75

Did the following monthly routine maint. on the computer A₁-A₆ T.C.L. 3 1/2 hrs. also did the cal. of the room temperature thermostat for room temp alarm & shutdown.

5-9-75

Did the following Quarterly routine maint. on the computer A₂-A₆, B₁ & B₂ T.C.L. 2 1/2 hrs.

5-14-75

Replaced a bad fan motor in the middle interface rack. T.C.L. 3 1/2 hrs.

5-20-75

Recal. the room temperature thermostat for a room temperature warning at 80°F. T.C.L. 1 Hr.

5-23-75

Chkd the power cord to the computer to see if it was worn or would get a A-C failure when moved. Everything chkd out ok.

A.C.F. 1/2 Hr.

6-20-75

Did the monthly routine maint of the computer

2 Hr. A.C.F.

7-14-75

The computer bombed out because of a A-C power interruption the ~~night~~ night before. Turned the power on-off 15 times without an error.

Run the Pwr. Fail - auto restart tape + chkd the 'A' - accumulator (alt had 102).

Run the Memory Worst Case tape for 45 min without an error. A.C.F. (2 Hrs.)

7-23-75

Monthly routine maint. of the computer
A2 - A6. Chk. the Cal. of the room
Temp. Thermostat. A.C.F. (4 Hrs.)

8-8-75

Did the following annually routine maint. on the computers A2-A6, B1, B2, C2, C5, D5

Power supply voltages

Model 222	Ripple	Model 221	Ripple
-6 Volts = 5.86	2 mV.	3.6 Volts = 3.60	2.0 mV.
-10 Volts = 9.61	2.6 mV	5.0 Volts = 5.03	2.95 mV.
-16 Volts = 14.85	345 mV.	Model 223	Ripple
+40 Volts = 32.97	2.9 V.	3.6 = 3.602	.62 mV.
+16 Volts = 17.35	1.65 mV.	Mode 223 (Far right)	
35 Volts = 33.08	3.3 mV.	3.6 Volts = 3.595	- 2.5 mV.
21 Volts = 21.00	.52 mV.		(Volts. T.C.D.)

8-11-75

Did the following annually routine maint. on the computers. C3, ~~C4~~ T.C.D. 4Hrs.

8-12-75

Did the following annually routine maint. on the computers. C4, P1, P2, D3, D4, D7 6Hrs. T.C.D.

9-25-75 Did the following monthly routine maint. of the computer. A₁-A₆. T.C.L. 2Hrs.

10-10-75 Did the following monthly routine maint. of the computer A₁-A₆ T.C.L. 2Hrs.

11-21-75 Did the following ~~monthly~~ quarterly routine maint. of the computer. A₂-A₆, B₁ & B₂. T.C.L.

12-17-75

Had a bomb out on the night of 12-16-75. Run the composite diagnostic program tape to ck out the computer. Everything checked out ok. T.C.L. 4Hrs.

12-19-75 Did the following monthly routine maint. of the computer. A₁-A₆ T.C.L. 2Hrs.

1-30-76 Did the following monthly routine maint. of the computer A₁-A₆ T.C.L. 2Hrs. Also replaced a bad muffin fan at the bottom East corner of the upper 8K memory rack.

2-13-76

Did the following quarterly routine
maint. of the computer. A2-A6, B1 & B2 T.C.L. 4 hrs.

2-23-76

Reprogrammed the computer with
a new program tape dated 2-12-76 A.C.P.

3-12-76

at 5:48 PM the day before there was
a A.C. power failure and the computer failed
to go back into remote mode.

Checked the power fail - auto reset circuits
using the data control sta. test tape.

Also turned the power on + off to the solution
10 times without the problem. Everything checked
out ok. 2 hrs. T.C.L.

3-29-76

Did the following monthly routine
maint. of the computer A1-A6 T.C.P. 2 hrs.

4-15-76 Did the following monthly routine
maint. of the computer A1-A6 T.C.L. 2 hrs.

4-28-76

Reprogrammed the computer with a new program tape dated 4-22-76 T.C.L. 1 1/2 hrs.

5-2-76

Replaced the Rixon modem with a modified one from the shop at STA. 106. Did the following quarterly routine maintain the computer - A1-A6, B1 & B2. T.C.L.

6-11-76

The % of transmission from the computer to Chicago was low the last 2 or 3 nights. Found a bad rixon modem cord and replaced it with one from the shop at sta. 106. Ran a test with the shop at sta. 106 for 1 1/2 hrs. and everything look good. T.C.L. 2 1/2 hrs.

10-26-81 Replaced a bad Model 221 3.6+5 Volt
power supply. Got a replacement from
106. Reset 3.6 +5 Volt pots.
Tracy Lisk