

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4715-02
<b>Description</b>	Bisync
<b>Model</b>	Model II
<b>Stock No.</b>	26-4715 Version 1.0
<b>Date</b>	Dec. 30, 1981
<b>Page 1 of</b>	1

### Problem

The following patch allows the Model II, when operating in a 3275 polled environment, to respond to EOT's. This will allow multiple Model II's, emulating 3275's, to operate on the same line with specific or general polling, as long as the Control Unit Addresses are unique.

### Solution

At TRSDOS READY, apply the following patch.

PATCH BIS3270 A=7D40 F=CC607D C=0000000