CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	15Ø7-Ø2
Description	S & P STOCKPACK
Model	Model I
Stock No.	26-15Ø7 Version 1.Ø
Date	May 5, 1981
Page 1 of	1

Problem

On CREPORT/BAS line 35 refers to a nonexistent line 9ØØ. In the MERGE program line 52Ø ends in a comma. Line 22ØØ of PTMAINT is incorrect.

Solution

The problem is corrected by following the steps listed below.

1. Backup the diskette(s) and make the changes on the Backup copy of the program.
2. In BASIC load the program by typing LOAD"PTMAINT".
3. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

```
Old Line: 22ØØ IF(NT=3ØORLN=3Ø)THENP7%=1:GOSUB1975:GOTO2Ø6ØELSE
          GOSUB91Ø:C%(3)=CVI(B$(3)):NL=C%(3):NL=NL+1:NT=NT+1:
          P8=NT:R$(P8)=FNA$(25):PRINT@183,"LOT: ";NL:
          L(NL,4)=Ø:PRINT@28Ø,"--VALUE--":LN=NL:FORK=1TO4:
          GOSUB3ØØ:IFK$="@"THENGOSUB197Ø:NL=NL-1:GOTO2Ø6ØELSENEXTK:GOSUB5

New Line: 22ØØ IF(NT=3ØORLN=3Ø)THENP7%=1:GOSUB1975:GOTO2Ø6ØELSE
          GOSUB91Ø:C%(3)=CVI(B$(3)):NL=C%(3):NL=NL+1:NT=NT+1:
          P8=NT:R$(P8)=FNA$(25):PRINT@183,"LOT: ";NL:
          L(NL,4)=Ø:PRINT@28Ø,"--VALUE--":LN=NL:FORK=1TO4:
          GOSUB3ØØ
```

CUSTOMER SERVICE BULLETIN

ADDITIONS (Type the line followed by an <ENTER>)

2201 IFK$="@"THENGOSUB1970:NL=NL-1:GOSUB2060ELSENEXTK:
GOSUB510

4. Type SAVE"PTMAINT" to save the changes in the program.
5. Load the next program by typing LOAD"CREPORT/BAS".
6. Make the following corrections:

DELETIONS (Type the line number and press <ENTER>)

35

7. Type SAVE"CREPORT/BAS" to save the changes in the program.
8. Load the next program by typing LOAD"MERGE".
9. Make the following corrections:

CHANGES (Edit the line number by referring to the owners manual)

Delete the comma at the end of line 520, or retype the line.

10. Type SAVE"MERGE" to save the changes in the program.
11. At TRSDOS Ready, make a backup copy of the corrected diskette.