CUSTOMER SERVICE BULLETIN

Radio Shack®

CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	159Ø-11
Description	SuperSCRIPSIT
Model	MODEL III
Stock No.	26-159Ø Version Ø1.Ø2.Ø7
Date	March 23, 1984
Page 1 of	1

Problem

Conversion of ASCII text into SuperSCRIPSIT, and problems relating to scrambled or garbage text within a document. These patches fix problems relating to paragraph arrays, the symptoms of which are many and varied. These patches will not fix a document that has exhibited the above problems, they are "after the fact" patches and will only stop the problem from occuring in a new document.

        * *   THE FOLLOWING PATCHES ARE <u>REQUIRED</u>!   * *

Solution

At TRSDOS READY, type:

```
PATCH SCRIPSIT/CMD (ADD=7ØEB,FIND=1D67,CHG=FØ7C)
PATCH SCRIPSIT/CMD (ADD=7CFØ,FIND=ØØØØØØØØ,CHG=7EFEFF28)
PATCH SCRIPSIT/CMD (ADD=7CF4,FIND=ØØØØØØØØØØ,CHG=Ø3CD1D67C9)
PATCH SCR17/CTL (ADD=8EC7,FIND=37,CHG=38)
```

After the PATCHES from this bulletin have been applied the Version number will be Ø1.Ø2.Ø8. Please make the necessary entry in you Version Log.