CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4503-3
Description	Payroll
Model	Model II
Stock No.	26-4503 Version 1.0
Date	July 28, 1980
Page 1 of	1

Problem

The payroll program for the Model II sometimes does not round properly.

Solution

The problem is corrected by following the steps listed below.

1. Backup the diskette(s) and make the changes on the Backup copy of the program.
2. In BASIC load the program by typing LOAD"INPUT".
3. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

Old Line: 820 E#(I)=INT(H#(I)*R#(I)*100#+.05#)/100#:GOTO840

New Line: 820 E#(I)=INT(H#(I)*R#(I)*100#+.5#)/100#:GOTO840

4. Type SAVE"INPUT" to save the changes in the program.
5. At TRSDOS Ready, make a backup copy of the corrected diskette.