CUSTOMER SERVICE BULLETIN

Problem

This program requires modifications as described below before it can be FCOPYED for hard disk use.

* * *   These patches are required.   * * *

Solution

At TRSDOS READY, apply the following patches to correct the above problem.

```
PATCH RSBASIC/LIO A=377D F=FD56Ø9FD5EØ8 C=Ø147ØØØ9ØØØØ
PATCH RSBASIC/LIO A=3786 F=ED53 C=ØØ22
PATCH RSBASIC/OLF R=156 B=126 F=FD56Ø9FD5EØ8 C=Ø147ØØØ9ØØØØ
PATCH RSBASIC/OLF R=156 B=135 F=ED53 C=ØØ22
```

When RUNBASIC is chaining a series of programs under the 4.Ø or 4.1 Hard Disk operating system, it will give an error 25 (PASSWORD PROTECTION) when it attempts to open the ISAM module a second time. This patch will correct this problem.

```
PATCH RUNBASIC A=2AF2 F=11612B C=CD9D2B
PATCH RUNBASIC A=2B9D F=ØØØØØØØØØØØØØØØØØØØØ C=11612B2323233652C9
```