CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	61Ø1-Ø1
Description	COBOL RUNTIME
Model	Model 16/Enhanced II
Stock No.	26-61Ø1 Version 1.Ø
Date	September 28, 1982
Page 1 of	1

Problem

The following two patches need to be applied to 26-61Ø1 prior to your attempting to use it.

Model 16 and Enhanced Model II:
Apply these patches to the single-sided diskette labeled COBOL RUNTIME.

* *   THESE PATCHES ARE REQUIRED!   * *

Solution

STEPS TO FOLLOW

1.   Backup the diskette to be patched.
2.   At TRSDOS-II Ready, type:

PATCH RUNCOBOL/SYS R=2 B=199 F=Ø1 C=Ø2

3.   Check the patch on the screen with the patch above.
     Backspace and make corrections if necessary.
4.   Press <ENTER>.
5.   The screen should display PATCH COMPLETE and then TRSDOS-II Ready.
6.   At TRSDOS-II Ready, type:

PATCH RUNCOBOL/SYS R=23 B=22Ø F=44 C=45

7.   Repeat steps 3-5 for patch number two.
8.   Backup the patched diskette.