

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1562-4
Description	Profile
Model	Model I
Stock No.	26-1562 Version 1.0
Date	June 10, 1980
Page 1 of	1

Problem

The program on page 25 of the manual is incorrect.

Solution

The correction of the line is:

Old Line: 20 PR=1+INT((N-1)/4): LR=(N-1)-PR

New Line: 20 PR=1+INT((N-1)/4): LR=(N-1)-(PR-1)*4