

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	<u>4517-03</u>
Description	<u>PROFILE PLUS</u>
Model	<u>Model II</u>
Stock No.	<u>26-4517 Ver. 01.01.00</u>
Date	<u>May 4, 1983</u>
Page 1 of	<u>1</u>

Problem

* This Customer Service Bulletin applies to Version 01.01.00. See CSB 4517-02 for the same problem on Version 01.00.00

Individual record suppression (CTRL-9) in detail lines of a report causes an unexpected title print every 249 records.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

Apply the patches to the Profile Plus master diskette and working copies that were created when the upgrade (26-4517) was applied to Profile (26-4512).

Version 01.01.00 of Profile Plus

To update the version number to 01.01.01, apply the following patch.

```
PATCH M A=3995 F=312E312E30202020 C="01.01.01"
```

For the problem, apply the following patches.

```
PATCH PRINT/EFC A=29F2 F=CAF929 C=CA355E
```

```
PATCH PRINT/EFC A=5E35 F=00000000000000000000 C=2A2B442B222B44C3F929
```

After patches from this Bulletin have been applied, the version number will be 01.01.01. Please make the necessary entry in your Version Log.