

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	KIRK BRIDE
Description	LOST DIRECTORY
Model	II
Stock No.	26-4531 (SCRIP.S.T)
Date	10/6/82
Page 1 of	1

**Problem** LOST DIRECTORY DUE TO SHORT IN KEYBOARD  
CONNECTING CABLE FROM COMPUTER

**Solution** BLOCK DEFINE PAGE THAT YOU WANT TO PUT ON  
NEW DISKETTE IN DRIVE Ø  
DRIVE Ø = NEW DISKETTE AND NEW TITLE (CLOSE TO NAME OF THE  
DAMAGED DISKETTE. USING F1 KEY TO START NEW  
DOCUMENT)

DRIVE 1 = DAMAGED DISKETTE WITH DOCUMENT AND NO DIRECTORY  
CONTROL R (REPLACE PAGE)

AFTER DEFINING PAGE WITH BLOCK MARKERS YOU MUST LOAD  
IT INTO R.A.M. AND THEN REPLACE PAGE ONTO NEW DISK  
ETTE WITH NO INFO JUST DOCUMENT NAME.