

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4706-01
Description	BASIC Runtime
Model	Model II
Stock No.	26-4706 Version 1.2
Date	May 21, 1982
Page 1 of	1

Problem

This program requires modifications as described below before it can be PCOPYED for hard disk use.

* * * These patches are required. * * *

Solution

At TRSDOS READY, apply the following patches to correct the above problem.

```
PATCH RSBASIC/LIO A=377D F=FD5609FD5E08 C=014700090000  
PATCH RSBASIC/LIO A=3786 F=ED53 C=0022
```