

CUSTOMER SERVICE BULLETIN

Subject 26-4716 Bisynchronous Comm. Page 1 Of 1

- 1) This Bulletin is to be placed behind tab 26-4716. It is intended to replace the Bulletins listed below:

4716-Ø1

4716-Ø2

- 2) IT IS IMPERATIVE THAT YOU REMOVE FROM THIS MANUAL THE BULLETINS REFERENCED ABOVE. Those bulletins should be retained in an archive file for possible reference. The bulletins being removed are not relevant to the current version of this package. They have been incorporated into the 3.4 version of this software. If upgrades are required, order through the Warranty Exchange program.
- 3) If a problem is found (or suspected) in the current version of this package, notify Computer Customer Services to file a Problem Report. If you do not understand the intent of this bulletin, call Computer Customer Services for clarification.


SOFTWARE COORDINATOR