

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No. 4910-6  
Description BASIC NAME  
Model Model II  
Stock No. 26-4910 Version 2.0  
Date November 23, 1980  
Page 1 of 1

### Problem

In the Model II 1.2 Basic Manual, there are several mistakes on page 3/12A. The command that is on the page is NAME. If the syntax is followed as stated, a SN error occurs.

### Solution

Old Syntax

NAME OLDNAME TO NEWNAME

only will work as follows:

NAME OLDNAME AS NEWNAME

Also in the examples, it uses RENAME instead of the command NAME, which should be used.