

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No. 4910-8
Description TRSDOS Terminal
Model Model II
Stock No. 26-4910 Version 2.0
Date November 5, 1980
Page 1 of 1

Problem

While using the "G" (Get Disk File Into RAM) with a variable-length record file, 1 extra byte was inserted before every logical record.

Solution

The patch follows:

PATCH TERMINAL A=3723 F=FE4628 C=D65620

PATCH TERMINAL A=372A F=06004E23AFB9C004C9 C=474E230DC0E1C3F632