

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	61Ø1-Ø1
Description	COBOL RUNTIME
Model	Model 16/Enhanced II
Stock No.	26-61Ø1 Version 1.Ø
Date	September 28, 1982
Page 1 of	1

Problem

The following two patches need to be applied to 26-61Ø1 prior to your attempting to use it.

Model 16 and Enhanced Model II:

Apply these patches to the single-sided diskette labeled COBOL RUNTIME.

* * THESE PATCHES ARE REQUIRED! * *

Solution

STEPS TO FOLLOW

1. Backup the diskette to be patched.
2. At TRSDOS-II Ready, type:

```
PATCH RUNCOBOL/SYS R=2 B=199 F=Ø1 C=Ø2
```

3. Check the patch on the screen with the patch above. Backspace and make corrections if necessary.
4. Press <ENTER>.
5. The screen should display PATCH COMPLETE and then TRSDOS-II Ready.
6. At TRSDOS-II Ready, type:

```
PATCH RUNCOBOL/SYS R=23 B=22Ø F=44 C=45
```

7. Repeat steps 3-5 for patch number two.
8. Backup the patched diskette.