

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	6105-01
Description	TRSDOS II
Model	Model II/16
Stock No.	26-6105 Version 4.1
Date	August 13, 1982
Page 1 of	1

Problem

The TRSDOS II - 4.1 patches listed below should be used to alleviate a problem in the error recovery portion of BACKUP which, under certain circumstances, gives an ERROR 41.

* * THESE PATCHES ARE REQUIRED! * *

Solution

At IRSDOS READY, apply the following patches to correct the above problem.

PATCH BACKUP {R=9 B=142 F=DE C=D8}
PATCH BACKUP {R=9 B=227 F=DE C=D8}