



Sun Storage Fibre Channel Switch Firmware Version 7.4.0.11.00 Release Notes

For QLogic SANbox 5200 FC Switch
SANbox 5600 Series FC Switch
and Sun Storage Fibre Channel Switch 5802

Sun Microsystems, Inc.
www.sun.com

Part No. 820-4957-10
September 2008, Revision A

Submit comments about this document at: <http://www.sun.com/hwdocs/feedback>

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, U.S.A. All rights reserved.

Sun Microsystems, Inc. has intellectual property rights relating to technology that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed at <http://www.sun.com/patents> and one or more additional patents or pending patent applications in the U.S. and in other countries.

This document and the product to which it pertains are distributed under licenses restricting their use, copying, distribution, and decompilation. No part of the product or of this document may be reproduced in any form by any means without prior written authorization of Sun and its licensors, if any.

Third-party software, including font technology, is copyrighted and licensed from Sun suppliers.

Enterprise Fabric Suite and QuickTools are trademarks of QLogic Corporation.

Parts of the product may be derived from Berkeley BSD systems, licensed from the University of California. UNIX is a registered trademark in the U.S. and in other countries, exclusively licensed through X/Open Company, Ltd.

Sun, Sun Microsystems, the Sun logo, Java, AnswerBook2, docs.sun.com, StorageTek, and Solaris are trademarks or registered trademarks of Sun Microsystems, Inc., or its subsidiaries, in the U.S. and in other countries.

All SPARC trademarks are used under license and are trademarks or registered trademarks of SPARC International, Inc. in the U.S. and in other countries. Products bearing SPARC trademarks are based upon an architecture developed by Sun Microsystems, Inc.

The OPEN LOOK and Sun™ Graphical User Interface was developed by Sun Microsystems, Inc. for its users and licensees. Sun acknowledges the pioneering efforts of Xerox in researching and developing the concept of visual or graphical user interfaces for the computer industry. Sun holds a non-exclusive license from Xerox to the Xerox Graphical User Interface, which license also covers Sun's licensees who implement OPEN LOOK GUIs and otherwise comply with Sun's written license agreements.

U.S. Government Rights—Commercial use. Government users are subject to the Sun Microsystems, Inc. standard license agreement and applicable provisions of the FAR and its supplements.

DOCUMENTATION IS PROVIDED "AS IS" AND ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS AND WARRANTIES, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT, ARE DISCLAIMED, EXCEPT TO THE EXTENT THAT SUCH DISCLAIMERS ARE HELD TO BE LEGALLY INVALID.

Copyright 2008 Sun Microsystems, Inc., 4150 Network Circle, Santa Clara, California 95054, États-Unis. Tous droits réservés.

Sun Microsystems, Inc. possède les droits de propriété intellectuelle relatifs à la technologie décrite dans ce document. En particulier, et sans limitation, ces droits de propriété intellectuelle peuvent inclure un ou plusieurs brevets américains listés sur le site <http://www.sun.com/patents>, un ou les plusieurs brevets supplémentaires ainsi que les demandes de brevet en attente aux les États-Unis et dans d'autres pays.

Ce document et le produit auquel il se rapporte sont protégés par un copyright et distribués sous licences, celles-ci en restreignent l'utilisation, la copie, la distribution, et la décompilation. Aucune partie de ce produit ou document ne peut être reproduite sous aucune forme, par quelque moyen que ce soit, sans l'autorisation préalable et écrite de Sun et de ses bailleurs de licence, s'il y en a.

Tout logiciel tiers, sa technologie relative aux polices de caractères, comprise, est protégé par un copyright et licencié par des fournisseurs de Sun.

Enterprise Fabric Suite et QuickTools sont des marques de fabrique de QLogic Corporation.

Des parties de ce produit peuvent dériver des systèmes Berkeley BSD licenciés par l'Université de Californie. UNIX est une marque déposée aux États-Unis et dans d'autres pays, licenciée exclusivement par X/Open Company, Ltd.

Sun, Sun Microsystems, le logo Sun, Java, AnswerBook2, docs.sun.com, StorageTek, et Solaris sont des marques de fabrique ou des marques déposées de Sun Microsystems, Inc., ou ses filiales, aux États-Unis et dans d'autres pays.

Toutes les marques SPARC sont utilisées sous licence et sont des marques de fabrique ou des marques déposées de SPARC International, Inc. aux États-Unis et dans d'autres pays. Les produits portant les marques SPARC sont basés sur une architecture développée par Sun Microsystems, Inc.

L'interface utilisateur graphique OPEN LOOK et Sun a été développée par Sun Microsystems, Inc. pour ses utilisateurs et licenciés. Sun reconnaît les efforts de pionniers de Xerox dans la recherche et le développement du concept des interfaces utilisateur visuelles ou graphiques pour l'industrie informatique. Sun détient une licence non exclusive de Xerox sur l'interface utilisateur graphique Xerox, cette licence couvrant également les licenciés de Sun implémentant les interfaces utilisateur graphiques OPEN LOOK et se conforment en outre aux licences écrites de Sun.

LA DOCUMENTATION EST FOURNIE "EN L'ÉTAT" ET TOUTES AUTRES CONDITIONS, DÉCLARATIONS ET GARANTIES EXPRESSES OU TACITES SONT FORMELLEMENT EXCLUES DANS LA LIMITE DE LA LOI APPLICABLE, Y COMPRIS NOTAMMENT TOUTE GARANTIE IMPLICITE RELATIVE À LA QUALITÉ MARCHANDE, À L'APTITUDE À UNE UTILISATION PARTICULIÈRE OU À L'ABSENCE DE CONTREFAÇON.



Sun Storage Fibre Channel Switch Firmware Version 7.4.0.11.00 Release Notes

These release notes describe the known issues and release details that apply to Sun Storage Fibre Channel Switch firmware, version 7.4.0.11.00.

This document contains the following sections:

- [Version](#)
- [Known Issues](#)
- [Additional Information](#)
- [Contacting Support](#)

Version

Users who intend to use the Enterprise Fabric Suite™ 2007 application for Sun FC switches and directors with firmware version 7.4 must use Enterprise Fabric Suite 2007 build 7.04.08 or later.

Known Issues

The following table identifies the known issues in firmware version 7.4.0.11 and the QuickTools™ web applet for Sun FC switches and directors, version 7.04.08.

Firmware

Sun CR 6724192

When upgrading firmware while in maintenance mode, the message "gpg: WARNING: This key is not certified with a trusted signature ..." is displayed. This message is incorrect and may be ignored.

Sun CR 6724198

While running port and/or switch diagnostics, the user should not replace SFP media. Doing so may result in the clearing of media information.

QuickTools

Sun CR 6724200

QuickTools dialogs are modal (designed to stay on top of a parent window or pop to the top of a parent window when the parent window is selected.). On Solaris and Linux platforms, there is a known issue for the Java plug-in (bug #4739735) where the code to identify the parent frame doesn't work correctly. The dialog doesn't know who its parent is. The result is that all the dialogs act as if they were non-modal (they can come up or get behind their parent window and the parent is locked up by the dialog). This situation can occur when switching between other applications while using QuickTools or selecting the parent window while a child window is still open. If this occurs (a child window gets behind a parent window) the parent will appear non-responsive until the child window is closed. To resolve the situation use the Alt +Tab keys to change focus to the child window.

Sun CR 6724202

When using the Firefox 2.0 browser with Solaris10 and opening and closing help windows from the dialog boxes, the following message may be displayed: "Firefox is already running but is not responding. To open a new window, you must first close the existing Firefox process or restart your system." If this occurs, you must follow the instructions to continue opening help windows.

Additional Information

Read the following document files for more information:

- Firmware readme file (`readme_firmware_74011.txt`) at <http://sunsolve.sun.com>. The firmware readme file is included with patch ID 138907-01 for firmware version 7.4.0.11.00, for Sun Storage Fibre Channel Switch 5802.

The Sun Storage Fibre Channel Switch 5802 does not support connections to the following switches:

- SANbox 8
- SANbox 16
- SANbox2-8
- SANbox2-16
- SANbox2-64

Related Documentation

Online documentation is available at:

<http://docs.sun.com/app/docs/prod/switch.dir#hic>

Contacting Support

Sun Function	URL
Documentation	http://www.sun.com/documentation/
Support	http://www.sun.com/support/
Training	http://www.sun.com/training/
Service	http://www.sun.com/service/contacting/index.xml
